

# Download Merc 115 Manual Trim Lock

14 Legend Alpha 199 SCX 14 225 Merc Pro XS Listed 3/31/19P: 25 Fury, manual jackplate, Motorguide Tour 82#, HDS9 bow, HDS9 indash, tilt steering, pro trim, JumpStart system, hot foot, Smartcraft, MK345 3 bank charger, Bluetooth radio, custom EZ Loader trailer with new 255/45ZR18 tires in April 2018.17 Triton 19 TRX 17 200 Merc Pro XS Listed 4/6/19P: 24 Tempest Plus, Z-Lock manual jackplate, MK Fortrex 80#, HDS9 Gen3 w/structure scan, HDS7 Gen3 w/structure scan, Point1 GPS, rod storage in 2 compartments, hot foot, upgraded storage box pad.I have a 90 TLRV Yamaha with a 6H1 power tilt trim system I am experiencing no down pressure. it started leaking fluid one day so I ordered seals and o rings for it took it out worked a couple of days and stopped going down .then I replaced hydraulic pump, sub valves, and all relief valve seats and springs since and every o ring and seal again. still have the same problem could it be a worn or ...I have a 40 hp /force motor with power trim and tilt. It will go up but will not go down when I hit the down button. Up seems fine. I was able to get the motor down by doing the manual process, loosening screw and retightening it after it went down.